#### UNCLASSIFIED

#### AD NUMBER

AD376828

#### **CLASSIFICATION CHANGES**

TO: unclassified

FROM: confidential

#### **LIMITATION CHANGES**

#### TO:

Approved for public release, distribution unlimited

#### FROM:

Distribution: USGO: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

#### AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

#### THIS PAGE IS UNCLASSIFIED

376828

AEC RESEARCH AND DEVELOPMENT REPORT

SUPPORT ACENCY

Facsimile

Report



**ATOMIC ENERGY COMMISSION** 

UNITED STATES Reproduced by

Division of Technical Information

Oak Ridge, Jermessee 37831

**CONFIDENTIAL** 

This material contains information affecting the national defense of the United States within the meaning of the espionage laws, Title 18, U.S.C., Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

Inc. 10 01

ACCESSION TO BRIDE SECTION COME

NOT. 1°C. 700

NOT

IN ADDITION TO SECURITY REQUIREMENTS WHICH
APPLY TO THIS DOCUMENT AND MUST BE MET,
THE U.S. GOVERNMENT MUST HAVE PRIOR APPROVAL
OF THE DIRECTOR, DEFENSE ATOMIC SUPPORT AGENCY,
WASHINGTON, D.C. 20301.

# CONFIDENTIAL

# 

A)

TEST ABLE 1/1/8

(1) 1946 (1) 22D

REG. NO. 4

CONFIDENTIAL

DIRECTOR OF SHIP MATERIAL

JOINT TASK FORCE ONE

DI STRI BUTION LIMITED

OPERATION CROSSROADS,


(13000)

## CONFIDENTIAL

BUREAU OF SHIPS GROUP

TECHNICAL INSPECTION REPORT

Downgraded at 12 year intervals Not Astomatically Declassified. GROUP 3



CONFIDENTIAL CONFIDENTIAL 1909

APPROVED:

F.X. Forest, Captain, U.S.N.

USS 1.ST 220

Page 1 of 33 Pages

RESIDENCE OF THE ATOMIC ACT 1946

# CONFIDENTIAL

### TABLE OF CONTENTS

83 Commanding Officers Report (Appendix) -----Machinery Technical Inspection Report (Section II) - -Electrical Technical Inspection Report (Section III) - -Photographic Section (Section IV) Hull Technical inspection Report (Section I) ---Ship Characteristics Sheet - - - - -Midship Section - - - - - -Overall Summary of Damage

CONFIDENTIAL



USS 1.ST 220

Page 2 of 33 Pages

CONFIDENTIAL Security Information

### CONFIDENTIAL

SEIP CHARACTERISTICS

Building Yard: Chicago Bridge and fron Co., Seneca, Illinois.

Commissioned: 26 August 1943.

HOLL

Length Overall: 228 feet 0 inches.
Length on Waterline: 316 feet 0 inches.
Beam (extreme): 50 feet 0 inches.
Drafts at time of test: Fwd. 6 feet 1 inch.
Aft. 10 feet 3 inches.
Limiting Displacement: 4,080 ions.
Displacement at time of iest: 2,888 tons.

MAIN PROPULSION PLANT

Main Engines: Two General Motors Diesels, type, 12 - 567 A. One per main shaft. Reduction Gears: Type: "Falk" - Single reduction.

One per engine.
Propellors: Two are installed in ship.
Man Stafts: Two are installed in ship.
Ships Service Generators: Three - 100 KW. - 230
volts D.C. units are installed.

CONFIDENTIAL 1045

SOMFILE INTIAL

USS 1.ST 220

Page 3 of 33 Pages

TECHNICAL MEDICOTION REPORT

- Target Condition After Test.
- (a) Drafts after test, list, general areas of flooding, sources.

There was no flooding, hence no change in drafts or list.

HULL

MACHINERY

No comment.

ELECTRICAL

There was no structural damage in way of electrical

(c) Other damage.

Not observed.

MACHINERY

The machinery of this vessel was not damaged by Test A. The vessel shifted berths under her own power after Test A, at which time all machinery was tested.

ELECTRICAL

No damage occurred to electrical equipment due to Test A.

UBS L&T 220

Page 5 of 33 Pages

OVERALL SUMMARY

(b) Structural Damage.

None.

HULL

II. Forces Evidenced and Effects Noted.

(a) Host,

#### HOLL

Heat was scorched only in small local areas where it had been thickly applied. Manila lines made up on the starboard lifeline are generally scorched. Two fires started in manila line.

### MACHINERY

No evidence,

### ELECTRICAL

No evidence of heat in way of electrical equipment.

(b) Fires and Explocions.

#### HULL

board, burned. Two wash deck noses stowed at frame 88, starboard, on the after bulkhead of the deck house, burned completely. This fire ignited and completely destroyed the contents of an adjacent gear locker. Paint in the area is badly burned.

### MACHINERY

No evidence,

### ELECTRICAL

There was no fires or explosions in way of electrical

equipment.

Shock,

Page 6 of 33 Pages

USS LST 220

AULL

None.

### MACHINERY

No evidence

### ELECTRICAL

There was no evidence of shock in way of electrical

equipment.

(d) Pressure.

#### ТП.Т.

Soct was blown from ventilation ducts and there was some elastic deflection of the main deck.

### MACHINERY

No evidence.

### ELECTRICAL

There was no evidence of pressure in way of electrical equipment.

(e) Effects peculiar to the Atomic Bomb.

H

None.

MACHINERY

None.

USS LST 220

Page 7 of 33 Pages

### ELECTRICAL

Radiant heat was evident on exposed surfaces. No other effect peculiar to the Atom Bomb was noted. The radiant heat had no apparent effect on any electrical equipment,

Results of Test on Target.

(a) Effect on machinery, electrical, and ship control.

Not observed,

MACHINERY

Lone.

ELECTRICAL

No damage was apparent to electrical machinery or

ship control.

Effect on gunnery and fire control. ව

HULL

Not observed

MACHINERY

No comment.

ELECTRICAL

No damage was apparent.

Effect on watertight integrity and stability. છ

SECRET

USS 1.ST 220

Page 8 of 33 Pages

HULL

None.

MACHINERY

No comment.

ELECTRICAL

No electrical damage affected watertight integrity or

stability.

Effect on personnel and habitability. ਦ

Exposed personnel would probably have been injured by heat and radiation. Habitability is not affected.

MACHINERY

None.

ELECTRICAL

No electrical damage affected personnel or habitability.

Effect on fighting efficiency. <u>е</u>

Other than possible injury of exposed personnel, there would have been no effect on fighting efficiency.

MACHINERY

None.

ELECTRICAL

No electrical damage affected the fighting efficiency

of the vessel.

SECRET

USS 1.ST 220

Page 9 of 33 Pages

# Summary of Observer's Impressions and Conclusions.

No comment.

### MACHINERY

LST 220 was outside the effective range of the explosion during Test A.

### ELECTRICAL

distance of this vessel from the center of the blast are not such as to require special designs or installation arrangements for electrical No damage was evident on any electrical equipment on this reseal. It appears that the effects of the Atom Bomb at the

Preliminary Recommendations.

None.

MACHINERY

None.

ELECTRICAL

None.

Page 10 of 33 Pages

SECRET

USS 1.ST 220

# TECHNICAL INSPECTION REPORT

SECTION I - HULL

# GENERAL SUMMARY OF HULL DAMAGE

- Target Condition After Tost. H
- (a) Drafts after test; list; general areas of flooding, sources.

There was no flooding, hence no change in drafts

(b) Structural Damage.

or list.

None

(c) Other damage

Not observed.

Forces Evidenced and Effects Noted. Ħ

(a) Heat.

Heat emanated from a relative bearing of 120 degrees. Paint was scorched only in small local areas where it had been thickly applied. Manila lines made up on the starboard lifeline are generally scorched. Two fires started in manila line:

(b) Fires and Explosions.

A manila line made up on the lifeline at frame 11, starboard, burned. Two wash deck hoses stowed at frame 88, starboard, on the after bulkhead of the deck house, burned completely. This fire ignited and completely destroyed the contents of an adjacent gear locker. Paint in the area is badly burned.

SECRET

USS LST220

Page 11 of 33 Pages

(c) Shock.

None.

(d) Pressure.

Soot was blown from ventilation ducts and there was some elastic deflection of the main deck.

(e) Effects apparently peculiar to the Atom Bomb.

None.

III. Effects of Damage.

(a) Effect on machinery, electrical, and ship control.

Not observed.

(b) Effect on gunnery and fire control.

Not observed.

(c) Effect on watertight integrity and stability.

None

(d) Effect on personnel and habitability.

Exposed personnel would probably have been injured by heat and radiation. Habitability is not affected.

(e) Effect on fighting efficiency.

Other than possible injury of exposed personnel, there would have been no effect on fighting efficiency.

SECRET

USS LST220

Page 12 of 33 Pages

IV. General Summary of Observers' Impressions and Conclusions.

No comment.

 Prelimbary General or Specific Recommendations of Inspection Group.

None.

VL Instructions for loading the vessel specified the following:

ITEM

Fuel oil Diesel oil Ammulition Potable and reserve feed water Salt water ballast

Minimum 10% No restriction No restriction

Minimum

Details of the actual quantities of the various items aboard are included in Report 7, Stability Inspection Report, submitted by the ship's force in accordance with 'Instructions to Target Vessels for Tests and Observations by Ship's Force'' issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

SECRET

USS LST220

Page 13 of 33 Pages

# DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

The only hull damage is minor damage to paint caused by a small fire. A general view of the ship is shown on page 30.

B. Superstructure.

There is no significant damage. Dirt was shaken loose from inside ventilation ducts and was blown into interior spaces. A fire burnel paint on the outside of the deck house.

C. Turrets, Guns, and Directors.

No damage.

D. Torpedo Mounts, Depth Charge Gear.

Not applicatle.

. Weather Deck.

No damage. Scratch gages recorded about 3/4 inch elastic deflection of the main deck.

Exterior Hull.

No damage.

G. Interior Compartments (above w.l.).

No damage.

H. Armor Decks and Miscellaneous Armor.

Not applicable.

SECLET

USS 1.8T 220

Page 14 of 33 Pages

I. Interior Compartments (below w.l.).

No damage.

Underwater Hull.

÷

No damage.

247

No damage.

Tanks.

M

Flooding.

j

None.

M. Ventilation.

No damage. Dirt was blown from inside ventilation ducts into interior spaces.

N. Ship Control.

No damage.

Fire Control.

ਂ

No damage.

,

Ammunition Behavior.

ď,

No damage.

Ammunition Handling.

ď

No damage.

R. Strength.

No damage.

SECRET

!

UES 1.8T220

Page 15 of 33 Pages

### S. Miscellaneous.

It had been applied infairly thick coats. Manila line made up on the starboard lifeline is generally scorched. A manila hawser made up on the lifeline at frame 11, starboard, burned. Two cotton wash deck hoses stowed on the deck house bulkhead at frame 48, starboard burned. This fire ignited and completely burned the contents of an adjacent gear locker. Paint on the adjacent bulkhead is badly burned. (Photo: 2047-7, page 31).

# THE THE THE PROPERTY OF REPORT

### SECTION II - MACHINERY

# GENERAL SUMMARY OF MACHINERY DAMAGE

- Target Condition After Test.
- (a) Drafts after test; list; general areas of flooding, sources

No data taken by machinery group.

(b) Structural damage.

No comment.

(c) Other damage.

The machinery of this vessel was not damaged by Test A. The vessel shifted berths under her own power after Test A, at which time all machinery was tested.

II. Forces Evidenced and Effects Noted.

(a) Heat.

No evidence.

(b) Fires and explosions.

No evidence.

(c) Shock.

No evidence.

(d) Pressure.

No evidence.

SECRET

USS LST 220

Page 17 of 33 Pages

SECRET

Page 16 of 33 Pages

USS 1.ST 220

(e) Effects apparently peculiar to the atom bomb,

HOE.

III. Effects of Damage.

(a) Effect on machinery and ship control.

None.

(b) Effect on gumbery and fire control.

No comment.

(c) Effect on water-tight integrity and stability.

No comment,

(d) Effect on personnel and habitability.

None.

(e) Total effect on fighting efficiency.

None.

IV. General Summary.

LST 220 was outside the effective range of the explosion during Test  ${\bf A}$ .

V. Preilminary Recommendation.

USS LST 220

USS LST 220

Page 18 of 33 Pages

SECRET

# DETAILED DESCRIPTION OF MACHINERY DAMAGE

General Description of Machinery Damage. Ą

(a) Overall condition,

The overall condition of the machinery was not changed by Test A.

(b) Areas of major damage.

(c) Primary cause of damage in each area of major damage.

Not applicable.

(d) Effect of target test on overall operation of machinery plant. The Target test had no effect on the overall operation of the machinery plant. All machinery has been operated since the

B. Boilers.

The heating boiler and its appurtenance were not damaged by Test A.

C. Blowers.

Included under B.

D. Fuel Oil Equipment.

Included under B.

SECRET

Page 19 of 33 Pages

E. Bollar Feedwater Equipment.

Included under B.

F. Main Propulsion Machinery.

There is no damage. The engines operated satisfactorily when the vessel shifted berths after Test A.

G. Reduction Gears.

Undamaged. Performance was normal with the ship underway.

H. Shafting and Bearings.

Undamaged. Performance was normal with the ship underway.

I. Lubrication System.

The lubrication system has been tested under normal working conditions and is undamaged.

Condensers and Air Ejectors.

Not applicable.

K. Pumps.

All pumps have been tested under normal operating conditions. There is no damage.

L. Auxillary Generators (Turbines and Gears).

Not applicable.

M. Propellers

There is no damage apparent on visual examination from the surface of the water. Operation was normal with the ship underway.

SECRET

USS LST 220

SECRET

Page 20 of 33 Pages

N. Distilling Plant.

Undamaged. The plant has been tested for capacity and functions normally.

O. Refrigeration Plant.

Undamaged. The plant has been operated under normal service conditions, and functions normally.

P. Winches, Windlasses, and Capstans.

All deck equipment has been tested under normal load. No damage was revealed.

Steering Engine.

The steering engine is undamaged as indicated by test under normal operating conditions.

R. Elevators, Ammunition Hoists, etc.

Undamaged. The tank deck elevator has been tested, and functions normally.

Ventilation (Machinery).

Undamaged. All ventilating machinery is operating

normally.

T. Compressed Air Plant.

The air compressors have been tested Undamaged. for full pressure operation.

U. Diesels (Generators and Bcats).

1. No boats were aboard during the test.

**USS LST 220** 

Page 21 of 33 Pages

2. Generators #2 and #3 were operated under normal load after Test A.

There is no evidence of any damage. Generator #1 was not operable prior to the test, having been cannibalized. Its condition was not changed by the test.

V. Piping Systems.

Undamaged. All piping systems have been tested under normal working pressures.

W. Miscellaneous.

No damage is evident in the galley, laundry, or machine shop equipment.

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

Target Condition After Test.

(a) Drafts, list, general areas of flooding, sources.

1. Drafts and list were the same as before test A.

2. There was no flooding.

(b) Structural damage.

There was no structural damage in way of electrical equipment.

(c) Damage.

No damage occurred to electrical स्प्रामामा due

to test A.

Ħ

Forces Evident and Effects Noted.

(a) Heat.

No evidence of heat in way of electrical equipment.

(b) Fires and explosions.

There were no fires or explosions in way of electrical equipment.

(c) Shock.

There was no evidence of shock in way of electrical equipment.

SECRET

USS LST 220

USS 1.ST 220

Page 22 of 33 Pages

SECRET

Page 23 of 33 Pages

(d) Pressure.

There was no evidence of pressure in way of electrical equipment.

(e) Effects peculiar to the Atom Bomb.

Radiant heat was evident on exposed surfaces. No other effect peculiar to the Atom Bomb was noted. The radiant heat had no apparent effect on any electrical equipment.

III. Effects of Damage.

(a) Effect on electrical equipment and ship control.

No damage was apparent to electrical machinery or ship control.

(b) Effect on gunnery and fire control.

No damage was apparent.

(c) Effect on watertight integrity and stability.

No electrical damage affected watertight integrity or stability.

(d) Effect on personnel and habitability.

No electrical damage affected personnel or

(e) Total effect on fighting efficiency.

habitability.

No electrical damage affected the fighting efficiency of the vessel.

W. General Summary of Observers Impressions and Conclusions.

SECRET

USS LST 220

SECRET

Page 24 of 33 Pages

on this vessel. It appears that the effects of the Atom Bomb at the dis-tance of this vessel from the center of the blast are not such as to require special designs or installation arrangements for electrical equip No damage was evident on any electrical eq ment.

Recommendations.

None.

USS 1.ST 220

Page 25 of 33 Pages

### SECTION III

# PART C - INEPECTION REPORT

### SECTION C - ELECTRICAL

- General Description of Electrical Damage.
- (a) Overall condition.

The overall condition of the electric plant is the same as before the test.

(b) Areas of major damage.

None.

(c) Primary causes of damage in each area of major damage. None. (d) Effect of target test on overall operation of electric plant.

1. Ship's service generator plant: No effect.

2. Engine and boiler auxiliaries: No effect.

3. Electric propulsion: Not applicable.

Communications: No effect.

5. Fire control circuits: No effect.

6. Ventilation: No effect.

7. Lighting: No effect.

(e) Types of equipment most affected.

None.

Page 26 of 33 Pages

SECRET

B. Electric Propulsion Rotating Equipment.

Not applicable.

C. Electric Propulsion Control Equipment.

Not applicable.

D. Ship's Service Generators.

No damage.

E. Emergency Generators.

Not applicable.

. Switchboards and Distribution Panels.

No damage.

G. Wiring, Wiring Equipment and Wireways.

No dmage.

H. Transformers.

No damage.

I. Submarine Propelling Batteries.

Not applicable.

Portable Brieries.

No damage.

K. Motors, Motor Generator Sets and Motor controllers.

No damage.

SECRET

USS LST 220

USS 1.ST 220

Page 27 of 33 Pages

Lighting Equipment.

Searchilghts. K No damage

Degaussing Equipment.

No damage.

Gyro Compass Equipment. o

No damage.

PHOTOGRAPHS

TEST ABLE

SECTION IV

Sound Powered Telephones.

No damage.

Ship's Service Telephones. ď

Not applicable.

Announcing Systems. డ

No damage.

Telegraphs.

No damage.

T. Indicating Systems.

No damage.

U. - I.C. ard A.C.O. Switchboards.

Not applicable.

V. F.C. Switchboards.

Not applicable.

SECRET

SECRET

USS 1.ST 220

Page 29 of 33 Pages

Page 28 of 33 Pages

USS 1.ST 220




AA-CR-227-87-85. View from off starboard bow after Test A.

SECRET

USS LST-220

Fage 30 of 3? Pages



and the state of the damage, main deck, frame 48, ctarboard.

इ.स.च्य ६३ ०३ १३ इन्हरू

133 LST-220

APPENDIX

COMMANDING OFFICERS REPORT

TEST ABLE

Page 32 of 33 Pages

USS 1.ST 220

### CONFIDENTIAL

REPORT # 11

COMMANDING OFFICERS REPORT

SECTION I

The condition of LST 220 after test Able was very much the same as before. The drafts upon our return were the same, six (f) set forward and ten (f) feet aft, with a one (f) degree list to port. There was no evidence of any structural damage and all machinery was operable.

six (6) inch mooring hauser, forward on the starboard side was burned as were two fire hoses aft. The burning of the hoses caused a gear locker on the boat deck to catch on fire and its contents were destroyed. All lines and rigging on the starboard side were slightly charred, giving us a fairly accurate check on the direction of the blast in relation to this ship. This direction I would estimate as being from one hundred and twenty wild distance because only the lines as mentioned above showed any signs of the heat. Evidence of abnormal pressures were observed here however, all our vents and vent ducts were cleaned out, the soot being deposited throughout the interior of the ship.

All in all I would say that there were no peculiar effects to be noted. The ships distance from the center of the blast, approximately two miles, accounts for this no doubt. I think it entirely possible for personnel to have lived absard, below decks, during the explosion. With protective circling and some means of protection from the radiological effects we could have existed topoide at battle stations.

The water tight integrity, stability and fighting efficiency of this vessel were in no way affected by the explosion or the blast and heat resulting there from.



U.S.S. I.ST 220

Page 33 of 33 Pages

COMPIDENTIAL

# CAUTION

This Document Contains
ATOMIC WEAPONS INFORMATION

### NOTICE

This document contains atomic weapons information. Distribution is limited to recipients authorized by the Defense Atomic Support Agency (DOD) and/or the Division of Military Application (AEC)



#### Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

✓AD-366588 <b>4</b>	XRD-203-Section 12
AD-366589	XRD-200-Section 9
AD-366590 L	XRD-204-Section 13
AD-366591 <b>►</b>	XRD-183
<b>∠</b> AD-366586 <b>★</b>	XRD-201-Section 10
►AD-367487.	XRD-131-Volume 2-
✓AD-367516¥	XRD- <b>\$</b> 143 <b>~</b>
✓AD-367493 <b>്</b>	XRD-142 ►
AD-801410L ✔	XRD-138
AD-376831L 🗸	XRD-83
AD-366759	XRD-80
✓AD-376830L ❖	XRD-79 <b>✓</b>
AD-376828L 🌂	XRD-76✓
AD-367464.X	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
AD-367459 🗴	XRD-100 ✓

TRC

Subject: Declassification of Reports

AD-801406L ✓ XRD-114.

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

ARDITH JARRETT
Chief, Technical Resource Center